National Transportation Safety Board NTSB ID: LAX04LA269 Aircraft Registration Number: N16TN FACTUAL REPORT Occurrence Date: 07/16/2004 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 1658 PDT CA 95148 San Jose Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Newell RV-6A Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On July 16, 2004, at 1658 Pacific daylight time, an experimental amateur-built Newell RV-6A airplane, N16TN, overran the runway and impacted a perimeter fence during a precautionary landing at the Reid Hillview Airport of Santa Clara County (RHV), San Jose, California. The airplane was registered to, and operated by, the pilot under the provisions of 14 CFR Part 91 as a personal flight. The private pilot and passenger were not injured. The airplane was substantially damaged. Visual meteorological conditions prevailed and a flight plan was not filed for the cross-country flight. The flight originated from San Luis Obispo, California, approximately one hour prior to the accident, and was destined for Hayward, California.

During a telephone interview conducted by the National Transportation Safety Board investigator-in-charge, the pilot said the airplane was in cruise flight over RHV when he noticed the oil pressure gauge was reading low and was getting lower. He monitored the oil temperature gauge and noticed it was indicating a higher than normal temperature. The pilot concluded he was losing, or had lost, engine oil, and elected to declare an emergency and conduct a precautionary landing at RHV. During landing, the pilot said he "landed long," and could not stop the airplane prior to overrunning the end of runway 31R (3,101 feet long). The airplane impacted an airport perimeter fence and came to rest upright.

The pilot reported the airplane sustained structural damage to the wings, along with damage to the nose landing gear and the propeller. He examined the engine following the accident and noticed the oil line (from the oil cooler to the engine) had a "big leak." The pilot reported the engine's previous performance was "excellent," and he did not notice any abnormal oil consumption rates. The airplane was stored in a hangar and he never noticed any oil on the hangar floor prior to the accident.

According to the pilot, the airplane accumulated a total of 598.2 hours of flight time. The last inspection of the airplane was conducted on May 13, 2004, 16.6 hours prior to the accident.

In the Pilot/Operator Aircraft Accident Report (NTSB form 6120.1/2), under the section titled, "How Could This Accident Have Been Prevented", the pilot indicated that the use of aircraft certified hoses could have helped prevent the failure of the oil line. The pilot noted that amateur-built airplanes do not require the use of FAA certified parts.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX04LA269

Occurrence Date: 07/16/2004

AVIATION		Occurrence Type: Accident												
Landing Facility/Approach In	formation	•												
Airport Name			Airpo	rport ID: Airport Elevation				Runway Used Runwa			th	Run	way Width	
Reid Hill View Airport			RH\	/	133 Ft. MSL 31R				3101			75		
Runway Surface Type: Asphalt														
Runway Surface Condition: Dry														
Type Instrument Approach: NONE	Ē													
VFR Approach/Landing: Precaution	onary Landing													
Aircraft Information														
Aircraft Manufacturer Newell				Model/RV-6/						Serial 2230	Number 05			
Airworthiness Certificate(s): Expe	rimental (Special))	•							•				
Landing Gear Type: Tricycle														
Homebuilt Aircraft? Yes	Number of Seats:	2		Certified	d Max Gross V	1650 LBS Number			er of Er	ngines	: 1			
				Engine Manufacturer: Model/Series: Lycoming O-360-A1D									ed Power:) HP	
- Aircraft Inspection Information														
Type of Last Inspection			Date of Last Inspection Time Sir					ince Last Inspection			Airframe Total Time			
Annual			05/	05/2004 16.6 Hot						ours	ours 598.2 Hours			
- Emergency Locator Transmitter (ELT) Information													
ELT Installed? Yes ELT Operated? No						EL.	Γ Aided i	n Locating Ad	ccident S	Site? No)			
Owner/Operator Information														
Registered Aircraft Owner			,	Street A	ddress 3581 St	ar Ric	dae Roa	ıd						
Richard E. Crowe				City								ie	Zip Code 94542	
					Hayward CA 94542 Street Address									
Operator of Aircraft						s Reg	d Aircr	aft Owner						
Same as Reg'd Aircraft Owner			City						Stat	te	Zip Code			
Operator Does Business As:					Operator Designator Code:									
- Type of U.S. Certificate(s) Held: I	None													
Air Carrier Operating Certificate(s)	:													
Operating Certificate:					Operator	Certifi	cate:							
Regulation Flight Conducted Unde	r: Part 91: Genera	al Avia	tion											
Type of Flight Operation Conducted														
		FACT	UAL	REPO	RT - AVIAT	ION							Page 2	

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: LAX04LA269

Occurrence Date: 07/16/2004

AVIATION			Occurrence Type: Accident										
First Pilot	Information								•				
Name City State Date of Birth Ag										Age			
On File On Fil							le				n File	On File	70
Sex: M Seat Occupied: Left Principal Profession: Unknown Certificate Number: On File											•		
Certificate(s): Private													
Airplane Rating(s): Single-engine Land													
Rotorcraft/Glider/LTA: None													
Instrument	Rating(s): Airpl	ane											
Instructor F	Rating(s): None	е											
Type Rating	g/Endorsement fo	or Accident/In	ncident Aircra	ft? Yes			С	urrent Bie	nnial Flig	ht Revi	ew? 04/	2004	
Medical Ce	rt.: Class 3	Medica	al Cert. Statu	s: Valid Med	dicalw/ wa	aivers/lii	m.		Date	of Last I	Medical I	Exam: 11/200	3
		· ·											
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Airplane Single Engine Mult-Engine		Nigh	t	Ins Actual	Instrument simulated		Rotorcraft	Glider	Lighter Than Air
Total Time		1706	79	1706			49	4	3	200			
Pilot In Cor	nmand(PIC)	1548	79	1548									
Instructor													
Last 90 Day	ys	20	20	20									
Last 30 Day		6	6	6									
Last 24 Ho		1	1	1		 		. 5 (<u>_</u>			
Seatbelt Us	sed? Yes	Shou	llder Harness	Used? Yes			loxico	ology Perfo	ormed? N	10		Second Pilot?	No
Flight Pla	n/Itinerary												
	ght Plan Filed: N o	one											
Departure F						Т	State	Ai	port Ider	ntifier	Depa	arture Time	Time Zone
San Luis Obispo CA RHV 1550								PDT					
Destination							State	Ai	port Ide	ntifier			
Hayward State Airport Identifier CA HWD													
Type of Cle	earance: VFR												
Type of Air	space: Class	D											
Weather	Information												
Source of I	Briefing: Unkno	wn											
Method of	Briefing: Unkno	wn											
FACTUAL REPORT - AVIATION Page 3													

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX04LA269

Occurrence Date: 07/16/2004

Occurrence Type: Accident

	FIYBOR		Occurrent	,е туре.	Acciden	ι									
Weather Information															
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Dis	stance Fro	om Accid	dent Site	Site Direction From Accident Si			te			
RHV	1658	PDT	133 Ft.	. MSL				NM	Deg. N			ı. Mag.			
Sky/Lowes	st Cloud Condition:			Ft. AGL						Condition of Light: Day					
Lowest Ce	eiling: Broken	15000 Ft.	AGL	Visibil	lity:	25	SM	Altimeter: 29.91		29.91	"Hg				
Temperatu	ure: 28 °C [8 °C	8 °C Wind Direction: 310 Density Altitude:								Ft.				
Wind Spee	ed: 12		Weather Condtions at Accident Site: Visual Conditions												
Visibility (R	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	of Precip	itation:								
Restriction	ns to Visibility: None														
Type of Pre	ecipitation: None														
Accident Information															
Aircraft Dar	mage:	Aircraft Fire	Aircraft Fire:						n						
Classificati	Classification:														
- Injury Sur	mmary Matrix	Fatal Seri	rious Mino	or	None	TOTAL									
First Pi	ilot	<u></u>			1	_ 	1								
Second	d Pilot						7								
Studen	nt Pilot						7								
Flight I	Instructor						7								
Check	Pilot						7								
Flight E	Engineer						7								
Cabin A	Attendants						7								
Other C	Crew						7								
Passen	ngers				1		1								
- TOTAL /	ABOARD -				2		2								
Other G	Ground						7								
- GRAND	O TOTAL -				2		2								
		·													

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: LAX04LA269

FACTUAL REPORT	Occurrence Date: 07/16/2004	
FACTUAL REPORT AVIATION	Occurrence Type: Accident	
Administrative Information		
Investigator-In-Charge (IIC)		
Nicole L. Charnon		
Additional Persons Participating in This Accident/Incide	ent Investigation:	
	EACTIAL DEDODT AVIATION	5 -